

Marker magnetic switch failure

This is a [soft](#) alarm.

Description

The magnetic switch has been active for too long

Troubleshooting

From:
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_marker_magnetic_switch_failure?rev=1578908630

Last update: **2020/01/13 01:43**

