

# Motor missing pulses in a given direction

This is a [soft](#) alarm.

## Description

No movement detected was detected at all when a motor was commanded to move. The alarm indicates both which motor that has failed and in which direction.

## Troubleshooting

- Check that pulses are received from given motor
- Check that motor is turning

From:  
<https://wiki.envirologic.se/> - Envirologic Support Wiki

Permanent link:  
[https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa\\_missing\\_pulses?rev=1580632868](https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_missing_pulses?rev=1580632868)

Last update: **2020/02/02 00:41**

