

PCB communication watchdog triggered

This is a [hard](#) alarm.

Description

The control electronics (PCB) detected a communication lapse

Troubleshooting

Contact service

From:
<https://wiki.envirologic.se/> - Envirologic Support Wiki



Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_pcb_wd

Last update: **2020/07/14 09:31**