

PCB communication watchdog triggered

This is a [hard](#) alarm.

Description

The control electronics (PCB) detected a communication lapse

Troubleshooting

Contact service

From:
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tso_pcb_wd?rev=1578409905

Last update: **2020/01/07 07:11**

