

# Self test failed

This is a [soft](#) alarm. However, it might indicate that action needs to be taken before washing can start.

## Description

One of the PLC self tests failed during start up. The self tests mostly cover internal parts of the PLC but there is also one for the [backup battery](#) (low or missing).

## Troubleshooting

Contact service. The backup battery might need replacement if FW version is below 15.52.

From:

<https://13.53.123.107/> - **Enviologic Support Wiki**

Permanent link:

[https://13.53.123.107/doku.php/troubleshooting:alarm:tsa\\_self\\_test\\_failed](https://13.53.123.107/doku.php/troubleshooting:alarm:tsa_self_test_failed)

Last update: **2021/11/02 01:43**

