Software

When new software is available an update symbol  is shown on the screen. Go to settings to install the update. If you have any questions, push the question mark button on the screen or contact us.

See what version your robot runs on

The latest software for the operator panel (PLC) is denoted **1.15**. The latest firmware is denoted **15.40**.

The latest software for the control electronics (PCB) is denoted **1.20** (denoted 1.19 for older electronics revisions).

PLC software change log

1.15 (2020-06-11)

New features
Added support for undo from joystick (SHIFT1+SHIFT2 then WATER button = UNDO)
Added support Romanian language (separate configuration)
Added support Hungarian language (separate configuration)
Tower and telescope movements will now accept a difference of 10 pulses from target without alarming for getting stuck

Improvements
Automatic run remains paused after emergency stop has been reset
Removed possibility to save empty programs
Other functions are now blocked when wheels are toggled in manual mode
Min and max position for tower and arm removed from Service screen

1.13 (2019-12-19)

New features
Added support for Wi-Fi configured routers

1.12 (2019-11-19)

Improvements
Improved reliability of hose spreader performance

1.11 (2019-10-09)

New features
Added support for Spanish language
Added support for Dutch language

1.9 (2019-07-02)

New features
Added alarms for low and high pressure
Added setting for not going back to the first marker after the recipe is finished
Added support for German language
The robot now sends SMS if washing is aborted unexpectedly
Added support for Korean language

Improvements
Improved guidance when an update is available
Washing is now blocked if homing is not done or if all positions have been reset
Improved battery status accuracy
Improved low battery handling and prevention '

1.8 (2018-12-07)

New features
Added support for virtual markers

PCB software change log

1.20 (2019-05-02)

Softer ramping of power to the hose reel motor

Delay PLC power on

Updated current measurement algorithm

1.16 (2019-01-24)

Support for pressure sensor

PLC firmware change log

15.40

Manufacturer fixed issue with backup battery possibly being drained after quick power toggles

Manufacturer fixed issue with false failing selftests due to backup batteryand loss of data

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/service:software?rev=1607406969

Last update: **2020/12/07 21:56**