First marker not found within 500 pulses

This is a hard alarm.

Description

No marker was detected when searching for the first marker during automatic cleaning, location creation or teach-in. The marker needs to be detected within about 1.2 meters from the starting position of the robot.

Troubleshooting

- Check that the magnetic switch arm is in the correct position (both height and length)
- Check that the marker is mounted properly
- Check that the magnetic switch is working
- Check that the robot was placed within 1 m from the first marker
- Check that the distance from the magnetic switch to the marker is less than 10 cm

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_first_marker?rev=1578407750

Last update: **2020/01/07 06:35**