Marker magnetic switch failure

This is a soft alarm.

Description

The magnetic switch has been active for too long, indicating possible failure.

Troubleshooting

- Check that the magnetic switch is working
- Check cabling to the magnetic switch

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_marker_magnetic_switch_failure

Last update: **2020/07/14 10:43**