Motor missing pulses in a given direction

This is a soft alarm. However, the alarm will be accompanied by a robot stuck alarm.

Description

No movement detected was detected at all when a motor was commanded to move. The alarm indicates both which motor that has failed and in which direction.

Troubleshooting

- Check that pulses are received from given motor
- Check that motor is turning

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_missing_pulses?rev=1578909070

Last update: **2020/01/13 01:51**