Alarm Code:

21. Telescope not parked

Context where the error occurs:

The telescopic arm has not reached parking position when completing the teaching process or after a manual run.

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/cc:alarm_21

Last update: **2021/04/16 03:11**