Alarm Code:

9. Max amount of pulses stored

Context where the error occurs:

This alarm appears only during transport forwards/backwards. Limit switches limit other movements.

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/cc:alarm_9

Last update: **2021/04/16 02:56**