File operation failed during teach

This is a hard alarm.

Description

An error occurred while writing to program file during teach-in

Troubleshooting

Unfortunately, the program must be re-created (restart the robot first). Contact Envirologic if the problem persists.

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_file_operation_failed_during_teach?rev=1578408449

Last update: **2020/01/07 06:47**