File operation failed during teach

This is a hard alarm.

Description

An error occurred while writing to program file during teach-in

Troubleshooting

Unfortunately, the program must be re-created (restart the robot first). Contact Envirologic if the problem persists.