Motor missing pulses in a given direction

This is a soft alarm. However, the alarm will be accompanied by a robot stuck alarm.

Description

No movement detected was detected at all when a motor was commanded to move. The alarm indicates both which motor that has failed and in which direction.

Troubleshooting

- Check that pulses are received from given motor
- Check that motor is turning