No current detected for given function

This is a soft alarm.

Description

No movement detected was detected at all when a motor was commanded to move. At the same time, no significant current was measured.

Troubleshooting

- Check motor cabling

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_no_current

Last update: **2020/07/14 10:21**