PCB communication failure

This is a hard alarm.

Description

The control electronics (PCB) failed to answer a request from the operator panel (PLC)

Troubleshooting

Contact service

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_pcb_com_failure?rev=1578409831

Last update: **2020/01/07 07:10**