Self test failed

This is a soft alarm. However, it might indicate that action needs to be taken before washing can start.

Description

One of the PLC self tests failed during start up. The self tests mostly cover internal parts of the PLC but there is also one for the backup battery (low or missing).

Troubleshooting

Contact service