Unexpected PCB reset

This is a hard alarm.

Description

The control electronics (PCB) has reset unexpectedly

Troubleshooting

Contact service

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_unexpected_pcb_reset?rev=1594187594

Last update: **2020/07/07 22:53**