Water pressure too low

This is a hard alarm.

Description

Low water pressure was detected. The water pressure was below about 50 bar for more than 2 minutes.

Troubleshooting

- Check the water hose for damages/leakage
- Check on the right side of hose reel if lock ring is positioned correctly
- Check swivel and hose that goes to the magnetic valve for damages/leakage (right hose reel side has to be taken off)
- Check that the pressure washer delivers water with sufficient pressure
    - Check that the flow is sufficient to the pressure washer and that there is no too much water directed elsewhere in the facilities
    - Make sure the pressure washer is in good condition. Pressure washers needs service too.
- Check that the strainer at the end of the long hose is clean from debris

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:water_pressure_too_low

Last update: **2024/08/21 11:08**