

Alarm Code:

21. Telescope not parked

Context where the error occurs:

The telescopic arm has not reached parking position when completing the teaching process or after a manual run.

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

https://wiki.envirologic.se/doku.php/cc:alarm_21

Last update: **2021/04/16 03:11**

