

# Software



When new software is available an update symbol  is shown on the screen. Go to settings to [install the update](#). If you have any questions, push the question mark button on the screen or contact us.

[See what version your robot runs on](#)

The latest software for the operator panel (PLC) is denoted **1.16**. The latest firmware is denoted **15.50**.

The latest software for the control electronics (PCB) is denoted **1.22** (denoted 1.21 for older electronics revisions).

---

## PLC software change log

### 1.16 (2021-05-17)

#### New features

Delayed start of first recipe, set in hours

Robot tries to untangle stuck hose reel between recipes by moving forward 1000 pulses

Power to telescope automatically increased beyond position 375 if stuck

#### Improvements

Feedback on notification feature termination

Soft alarms are no longer flashed during automatic washing, but still found in alarm list

Hose spreader stops moving if hose reel has not moved for 5 s

Time limit for low water pressure alarm is increased to 120 s (from 30)

#### Fixed issues

Removed possibility to set 0 as last marker number

### 1.15 (2020-06-11)

#### New features

Added support for undo from joystick (SHIFT1+SHIFT2 then WATER button = UNDO)

Added support Romanian language (separate configuration)

Added support Hungarian language (separate configuration)

Tower and telescope movements will now accept a difference of 10 pulses from target without alarming for getting stuck

#### Improvements

Automatic run remains paused after emergency stop has been reset

Removed possibility to save empty programs

Other functions are now blocked when wheels are toggled in manual mode  
Min and max position for tower and arm removed from Service screen

## **1.13 (2019-12-19)**

### **New features**

Added support for Wi-Fi configured routers

## **1.12 (2019-11-19)**

### **Improvements**

Improved reliability of hose spreader performance

## **1.11 (2019-10-09)**

### **New features**

Added support for Spanish language

Added support for Dutch language

## **1.9 (2019-07-02)**

### **New features**

Added alarms for low and high pressure

Added setting for not going back to the first marker after the recipe is finished

Added support for German language

The robot now sends SMS if washing is aborted unexpectedly

Added support for Korean language

### **Improvements**

Improved guidance when an update is available

Washing is now blocked if homing is not done or if all positions have been reset

Improved battery status accuracy

Improved low battery handling and prevention '

## **1.8 (2018-12-07)**

### **New features**

Added support for virtual markers

---

## **PCB software change log**

## 1.22 (2021-03-19)

Faster start of hose reel motor

## 1.20 (2019-05-02)

Softer ramping of power to the hose reel motor  
Delay PLC power on  
Updated current measurement algorithm

## 1.16 (2019-01-24)

Support for pressure sensor

---

## PLC firmware change log

### 15.50

Manufacturer fixed issue where it was possible for the unit to get stuck while booting which could result in complete backup battery drain if left unresolved  
Manufacturer fixed issue where units were not shutting down properly when backup battery voltage was below 2.0 V

### 15.40

Manufacturer fixed issue with backup battery possibly being drained after quick power toggles  
Manufacturer fixed issue with false failing selftests due to backup battery and loss of data

From:  
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:  
<https://wiki.envirologic.se/doku.php/service:software?rev=1621240445>

Last update: **2021/05/17 01:34**

