

First marker not found within 500 pulses

This is a **hard** alarm.

Description

No marker was detected when searching for the first marker during automatic cleaning, location creation or teach-in.

Troubleshooting

- Check that the magnetic switch arm is in the correct position
- Check that the marker is mounted properly
- Check that the magnetic switch is working
- Check that the robot was placed within 1 m of the first marker

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tss_first_marker?rev=1571165542

Last update: **2019/10/15 11:52**

