

# First marker not found within 500 pulses

This is a [hard](#) alarm.

## Description

No marker was detected when searching for the first marker during automatic cleaning, location creation or teach-in. The marker needs to be detected within about 1.2 meters from the starting position of the robot.

## Troubleshooting

- Check that the [magnetic switch](#) arm is in the correct position (both height and length)
- Check that the marker is mounted properly
- Check that the [magnetic switch](#) is working
- Check that the robot was placed within 1 m from the first marker
- Check that the distance from the [magnetic switch](#) to the marker is less than 10 cm

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

[https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa\\_first\\_marker?rev=1578407750](https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_first_marker?rev=1578407750)

Last update: **2020/01/07 06:35**

