

Marker magnetic switch failure

This is a [soft](#) alarm.

Description

The magnetic switch has been active for too long, indicating possible failure.

Troubleshooting

- Check that the magnetic switch is working
- Check cabling to the magnetic switch

From:
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tss_marker_magnetic_switch_failure?rev=1578908695

Last update: **2020/01/13 01:44**

