

# Motor missing pulses in a given direction

This is a [soft](#) alarm. However, the alarm will be accompanied by a [robot stuck](#) alarm.

## Description

No movement detected was detected at all when a motor was commanded to move. The alarm indicates both which motor that has failed and in which direction.

## Troubleshooting

- Check that pulses are received from given motor
- Check that motor is turning

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

[https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tss\\_missing\\_pulses?rev=1578909070](https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tss_missing_pulses?rev=1578909070)

Last update: **2020/01/13 01:51**

