No current detected for given function

This is a soft alarm.

Description

No movement detected was detected at all when a motor was commanded to move. At the same time, no significant current was measured.

Troubleshooting

· Check motor cabling

From

https://wiki.envirologic.se/ - Envirologic Support Wiki

Permanent link:

https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsa_no_current?rev=1580634503

Last update: 2020/02/02 01:08

