

# Self test failed

This is a [soft](#) alarm. However, it might indicate that action needs to be taken before washing can start.

## Description

One of the PLC self tests failed during start up. The self tests mostly cover internal parts of the PLC but there is also one for the [backup battery](#) (low or missing).

## Troubleshooting

Contact service

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

[https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tss\\_self\\_test\\_failed?rev=1599208902](https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tss_self_test_failed?rev=1599208902)

Last update: **2020/09/04 01:41**

