

# Robot restarts unexpectedly

## Description

If the message “Initializing, please wait” does not disappear within 20 seconds after the robot operators panel has booted.

## Troubleshooting

The issue is most probable lacking communication between panel and circuit board. Cable and connectors needs to be checked by trained service personnel.

From:  
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:  
[https://wiki.envirologic.se/doku.php/troubleshooting:no\\_alarm:robot\\_restarts?rev=1598244263](https://wiki.envirologic.se/doku.php/troubleshooting:no_alarm:robot_restarts?rev=1598244263)

Last update: **2020/08/23 21:44**

