

# Over current detected

This is a [soft](#) alarm.

## Description

The total current consumption has gone over 18 A.

## Troubleshooting

- Check that idle current is about 0.5 A.
- Check that no motors run overloaded, ie. check that the load has not increased due to mechanical failure, wear etc.
- Check for short circuits in motor cabling.

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

<https://wiki.envirologic.se/doku.php/troubleshooting:alarm:tsovercurrentdetected>

Last update: **2020/07/14 09:31**

