

Software



When new software is available an update symbol is shown on the screen. Go to settings to [install the update](#). If you have any questions, push the question mark button on the screen or contact us.

[See what version your robot runs on](#)

The latest software for the operator panel (PLC) is denoted **1.15**. The latest firmware is denoted **15.30**.

The latest software for the control electronics (PCB) is denoted **1.20** (denoted 1.19 for older electronics revisions).

PLC software change log

1.15 (2020-06-11)

New features

Added support for undo from joystick (SHIFT1+SHIFT2 then WATER button = UNDO)

Added support Romanian language (separate configuration)

Added support Hungarian language (separate configuration)

Tower and telescope movements will now accept a difference of 10 pulses from target without alarming for getting stuck

Improvements

Automatic run remains paused after emergency stop has been reset

Removed possibility to save empty programs

Other functions are now blocked when wheels are toggled in manual mode

Min and max position for tower and arm removed from Service screen

1.13 (2019-12-19)

New features

Added support for Wi-Fi configured routers

1.12 (2019-11-19)

Improvements

Improved reliability of hose spreader performance

1.11 (2019-10-09)

New features

Added support for Spanish language

Added support for Dutch language

1.9 (2019-07-02)

New features

Added alarms for low and high pressure

Added setting for not going back to the first marker after the recipe is finished

Added support for German language

The robot now sends SMS if washing is aborted unexpectedly

Added support for Korean language

Improvements

Improved guidance when an update is available

Washing is now blocked if homing is not done or if all positions have been reset

Improved battery status accuracy

Improved low battery handling and prevention '

1.8 (2018-12-07)

New features

Added support for virtual markers

PCB software change log

1.20 (2019-05-02)

Softer ramping of power to the hose reel motor

Delay PLC power on

Updated current measurement algorithm

1.16 (2019-01-24)

Support for pressure sensor

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

<https://wiki.envirologic.se/doku.php/service:software?rev=1594362402>

Last update: **2020/07/09 23:26**

