

**Alarm Code:**

9. Max amount of pulses stored

**Context where the error occurs:**

This alarm appears only during transport forwards/backwards. Limit switches limit other movements.

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

[https://wiki.envirologic.se/doku.php/cc:alarm\\_9](https://wiki.envirologic.se/doku.php/cc:alarm_9)

Last update: **2021/04/16 02:56**

