


Cable OP box

Part number: 989209M

Part of [Junction box assembly](#)



| ITEM | DESCRIPTION | PART NUMBER | QTY |
|------|------------------------|-------------|-----|
| 1 | Hybrid cable | 989209 | 1 |
| 2 | Cable gland M20 | 981018 | 1 |
| 3 | Shrink tube 5.2 mm | 45517 | 2 |
| 4 | Cable gland M20 PVC | 981037 | 1 |
| 5 | Cable M12 | 989204 | 1 |
| 6 | Switch, emergency stop | 989244 | 1 |
| 7 | Joint, emergency stop | 989223 | 1 |
| 8 | Crimp SPOX | 989212 | 2 |
| 9 | Molex SPOX | 989211 | 1 |
| 10 | End sleeve | 981042 | 1 |
| 11 | Cable protector | 45527 | 1 |

| ITEM | DESCRIPTION | PART NUMBER | QTY |
|------|--------------------------------------|-------------|-----|
| 12 | Molex 6 | 989235 | 1 |
| 13 | Crimp female | 901169 | 6 |
| 14 | 4G Router power-cable | 989228K2 | 1 |
| 15 | Cable connector 0.75 mm ² | 45314 | 3 |
| 16 | Nut M20 | 981021 | 1 |

From:
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:
<https://wiki.envirologic.se/doku.php/service:spl:989209m-1?rev=1601281690>

Last update: **2020/09/28 01:28**

