

Robot loses positioning, homing or clock

Description

Lost position

If the robot does not position correctly during washing it could be due to any number of reasons.

Contact Service in order to check operators panel's [backup battery](#) status

TBD

From:
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/troubleshooting:no_alarm:lost_memory?rev=1600063348

Last update: **2020/09/13 23:02**

