

Description

The boom has lost its position and cannot raise fully, believing it is already at maximum pulse.

Troubleshooting

Move the ****boom**** to the absolute bottom. Check that the position is zeroed (0 or +1) automatically when it stops at the bottom.

If not zeroed, continue to hold the boom down-button until you receive a question.

Press "Yes" on the question.

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

https://wiki.envirologic.se/doku.php/troubleshooting:no_alarm:zero_boom_position?rev=1654762371

Last update: **2022/06/09 01:12**

