Description

The boom has lost its position and cannot raise fully, believing it is already at maximum pulse.

Troubleshooting

Move the boom to the absolute bottom. Check that the position is zeroed (0 or +1) automatically when it stops at the bottom.

If not zeroed, continue to hold the boom down-button until you receive a question.

Press "Yes" on the question.

This is also a part of the homing process.

From:

https://wiki.envirologic.se/ - Envirologic Support Wiki

Permanent link:

https://wiki.envirologic.se/doku.php/troubleshooting:no_alarm:zero_boom_position?rev=1654762664

Last update: 2022/06/09 01:17

