## No current detected for given function

This is a soft alarm.

## **Description**

No movement detected was detected at all when a motor was commanded to move. At the same time, no significant current was measured.

## **Troubleshooting**

• Check motor cabling

From:

https://13.53.123.107/ - Envirologic Support Wiki

Permanent link:

 $https://13.53.123.107/doku.php/troubleshooting: alarm: tsa\_no\_current$ 

Last update: 2020/07/14 10:21

