



| Items Number | Parts Number | Description | Quantity |
|--------------|--------------|---|----------|
| 1 | 1109201 | Chassi | 1 |
| 2 | 1109202 | Link | 1 |
| 3 | 409216 | Arm | 1 |
| 4 | 1101030 | Link | 2 |
| 5 | ISO 7089 - 6 | Washer M6 Ingen bricka | 1 |
| 6 | 941009 | Nut M6 | 1 |
| 7 | 409212 | Arm | 1 |
| 8 | 93187752M | Rear Wheel Driving Assembly | 1 |
| 9 | 409211 | Arm | 1 |
| 10 | 1107030M | Transport wheels complete | 1 |
| 11 | 1109205 | Arm | 1 |
| 12 | 409215 | Arm | 1 |
| 13 | 1107041 | Front Wheel Assembly | 1 |
| 14 | 941073 | Nut M10 | 10 |
| 15 | 409213 | Arm | 1 |
| 16 | 941021 | Screw M8 x 30 | 2 |
| 17 | 941020 | Nut M8 | 2 |

| Items Number | Parts Number | Description | Quantity |
|--------------|--------------|----------------------|----------|
| 18 | 941016 | Washer M8 | 4 |
| 19 | 901036 | Wall Mounted Bearing | 1 |
| 20 | 401059 | Plate | 1 |

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

https://wiki.envirologic.se/doku.php/chassi_below?rev=1573651123

Last update: **2019/11/13 05:18**

