



Items Number	Parts Number	Description	Quantity
1	1109201	Chassi	1
2	1109202	Link	1
3	409216	Arm	1
4	1101030	Link	2
5	ISO 7089 - 6	Washer M6 Ingen bricka	1
6	941009	Nut M6	1
7	409212	Arm	1
8	93187752M	Rear Wheel Driving Assembly	1
9	409211	Arm	1
10	1107030M	Transport wheels complete	1
11	1109205	Arm	1
12	409215	Arm	1
13	1107041	Front Wheel Assembly	1
14	941073	Nut M10	10
15	409213	Arm	1
16	941021	Screw M8 x 30	2
17	941020	Nut M8	2

Items Number	Parts Number	Description	Quantity
18	941016	Washer M8	4
19	901036	Wall Mounted Bearing	1
20	401059	Plate	1

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

https://wiki.envirologic.se/doku.php/chassi_below?rev=1573651123

Last update: **2019/11/13 05:18**

