


# Left box assembly

Part of [EVO Cleaner assembly 2 - 1109502](#)



| ITEM | DESCRIPTION            | PART NUMBER | QTY |
|------|------------------------|-------------|-----|
| 1    | Left box               | 1109208     | 1   |
| 2    | Flange bearing EFOM 20 | 901036      | 1   |
| 3    | Screw M8 x 25          | 941018      | 2   |
| 4    | Nut M8 Nyloc           | 941020      | 2   |
| 5    | Washer M8              | 941016      | 2   |

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

<https://wiki.envirologic.se/doku.php/service:spl:1109527-1?rev=1601211689>

Last update: **2020/09/27 06:01**

