


Left box assembly

Part number: 1109527

Part of [EVO Cleaner assembly 2 - 1109502](#)



ITEM	DESCRIPTION	PART NUMBER	QTY
1	Left box	1109208	1
2	Flange bearing EFOM 20	901036	1
3	Screw M8 x 25	941018	2
4	Nut M8 Nyloc	941020	2
5	Washer M8	941016	2

From:

<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:

<https://wiki.envirologic.se/doku.php/service:spl:1109527-1?rev=1601281049>

Last update: **2020/09/28 01:17**

