
Swivel with angle

Part of EVO Cleaner assembly 2 - 1109502 and Arm assembly



ITEM	DESCRIPTION	PART NUMBER	QTY
1	Repair kit	964021	1

From:
https://wiki.envirologic.se/ - **Envirologic Support Wiki**

Permanent link:
https://wiki.envirologic.se/doku.php/service:spl:961003v?rev=1601208161

Last update: **2020/09/27 05:02**