


# Swivel with angle

Part of [EVO Cleaner assembly 2 - 1109502](#) and [Arm assembly](#)



ITEM	DESCRIPTION	PART NUMBER	QTY
1	Repair kit	964021	1

From:  
<https://wiki.envirologic.se/> - **Envirologic Support Wiki**

Permanent link:  
<https://wiki.envirologic.se/doku.php/service:spl:961003v?rev=1601271662>

Last update: **2020/09/27 22:41**

